



WILLEM TWEE / POPPODIUM DECORATIONS AND SFX 2026

DECORATIONS AND SFX CONDITIONS

Special Effects

Any special effects are upon request ONLY.

Due to environmental and safety reasons the following special effects are PROHIBITED!

- The use of pyrotechnic effects, including sparklers (cold fire), is not allowed.
- The use of CO2 cannons is not allowed.
- The use of confetti is not allowed.
- The use of streamers is not allowed.

Please note that we do charge extra for cleaning costs related to special effects.

For this reason, any stage/party props that make a mess must be agreed to in advance.

Laser

The use of laser is upon request ONLY.

Due to safety reasons and space limitations all lasers of class 2M, 3R, 3B and 4 are PROHIBITED!

With normal use and in the absence of any additional optical instruments, lasers of class 1, 1M and 2 are allowed in consultation with the Willem Twee production department.

Decorations

- Placement
1. The placement of decorations always occurs in consultation with the Willem Twee production department.
 2. An appointment must be made with the Willem Twee production department regarding the arrival time of materials, setup, and the time when the material will be removed.
 3. Willem Twee does not have storage for deco materials. All decorations must be removed from the location no later than half an hour after the show.

Safety

1. All materials must be fireproof, which means that fabrics should be flame-retardant. (for more detailed information see our note about fire safety below)
2. Decorations must be hung higher than 2,5 meter unless the material is non-flammable or if there are no people underneath.
3. In the event of a fire in a piece of decoration above a part of the floor where people can be, no dripping may occur.
4. All hung materials must be securely fastened. Decors, fabrics, and decorative materials must be attached using CE-approved fastening materials.
5. Emergency exits must always remain clear of obstacles at all times.
6. Decorative materials cannot be attached to walls or doors using tape, nails, or staples.
7. Willem Twee will conduct an inspection round before the hall opens. The technician on duty will verify compliance with all safety requirements. In case of disagreement, the Willem Twee technician has the final say.

Damage to our property caused by graffiti, paint markers, or the use of the wrong type of confetti, tape, stickers, etc. will be charged to the organizers or band afterward.

Fire safety

The materials used to make the decoration should not pose a fire hazard. There is no fire hazard when the following notes are met:

1. The decoration has an afterglow duration of ≤ 15 seconds and a smouldering duration of ≤ 60 seconds.
2. The decoration is non-flammable.
3. The decoration makes a minor contribution to the fire hazard in the enclosed space.

You can test the fire safety of materials with a simple test yourself. Proceed as follows:

Take a sample of the material. Go outside and hold one end of the sample in a flame, such as from a lighter or match, for at least 5 seconds. Hold the sample with, for example, a metal tong and be careful not to burn yourself. If the sample catches fire, remove the flame. The material must meet the following conditions:

1. No droplets (burning or non-burning) are released during heating.

2. No soot flakes are released during heating.
3. The material does not flame for more than 15 seconds and glows for a maximum of 60 seconds after the flame is removed.

If the material does not meet these conditions, it should not be used or should be impregnated first.